



**HUATAI
MARINE**

CIRCULAR


www.huataimarine.com

pni.bj@huatai-serv.com

Duty Phone: +86 13701125026

Circular Ref. No.: PNI [2021] 13 (Revised Version)

Date: 17 December 2021



Updates on Fishery Farms at Lanshan, China, up to Dec. 2021

Reference is made to our last circular (Huatai Circular—PNI[2021]10 issued in Aug. 2021) on fishery farm claims at Lanshan, China. In order to keep our clients posted of the changes on the geographical extent of fishery farms in that sea area, we, from cases handled recently, and from consulting with local Oceanic and Fishery Bureau as well as the Village Committee of the local fishery farmers, prepared this circular.

The Latest Sketch of The Fishing Farms off Lanshan (named as A-I)



I. The New Accident Involved Fishery Farms (please refer to the Area I in red color in South West)

Last month, we received a claim raised by one of the Owners of fishery farms in Area I (See the red part of the diagram above.) which drew our first notification. After our further investigation, we note that there were few claims occurred in this area, but to be prudent, we kindly draw Master's special attention to this area. The coordinates of it are as follows:

Area I:

35°00.21' N, 119°32.72' E

35°00.10' N, 119°35.48' E

34°58.10' N, 119°38.87' E

34°57.91' N, 119°37.79' E

34°57.89' N, 119°32.50' E

II. Other Fishery Farms

For your easy reference, we listed the other 8 fishery areas as below:

Area A:

35°06'12.00"N, 119°50'16.00"E

35°03'18.00"N, 119°49'28.00"E

35°03'18.00"N, 119°46'48.00"E

35°06'12.00"N, 119°47'30.00"E

Area B:

35°05'41.18"N, 119°54'03.73"E

35°04'21.77"N, 119°54'03.82"E

35°04'46.97"N, 119°54'45.81"E

35°05'35.97"N, 119°54'45.75"E

Area C:

35°04'01.06"N, 119°52'29.91"E

35°03'26.77"N, 119°52'15.68"E

35°03'26.87"N, 119°53'56.63"E

35°04'01.14"N, 119°53'49.95"E

Area D (revised):

35°02' 30.0" N, 119°36' 11.0"E

35°02' 18.0" N, 119°45' 48.0"E

35°00'30.00"N, 119°45'48.00"E

35°01'18.00"N, 119°36'18.00"E

Area E:

35°00'36.00"N, 119°35'18.00"E

34°59'42.00"N, 119°44'48.00"E

34°57'30.00"N, 119°40'42.00"E

Area F:

35°11'23.43"N, 119°59'36.03"E

35°10'52.35"N, 119°59'36.03"E

35°10'52.34"N, 120°00'54.73"E

35°11'23.43"N, 120°00'54.74"E

Area G:

35°10' 52.40" N, 119°49' 58.07"E

35°10' 10.63" N, 119°49'42.15"E

35°10' 10.75" N, 119°51'20.11"E

35°10' 52.34" N, 119°51'32.20"E

Area H:

35-10'01.66N, 119-54'03.38E

35-09'19.73N, 119-53'52.84E

35-09'19.65N, 119-56'42.48E

35-10'01.58N, 119-56'32.59E

Please note: This latest circular should be the most up to date version for Lanshan fishery farms and should prevail over other previous circulars.

In addition, we still have the following recommendations to ships calling or passing Lanshan port in order to avoid fishery farm claims:

In route planning, kindly take into account the fishery farms described in our latest circulars with special attention and caution to area A and D (revised). In addition, before the ship's arrival at Lanshan port, kindly check with local agents about the route to enter the anchorage and the port, as well as the distribution of the fishery farms.

The vessels shall maintain a proper lookout, and keep close contact with the VTS center and the pilot station. In addition, the Master shall not simply follow the recommended route of the VTS and pilot station before the pilot's embarkation. The Master shall, in light of the available information, carefully observe the surrounding sea area, and pay particular attention to the **fishery working boats ahead that affect navigation** (there might be fishery farms nearby the boats), and then make the correct decision.

Should you have any query, please feel free to contact our Qingdao Office:

Huatai Insurance Agency & Consultant Service Ltd., Qingdao Branch

Tel: +86 532 8502 1883

Duty Mobile: +86 186 5328 9883

Email: qingdao@huatai-serv.com

Best regards,



LUO Yong

General Manager